





Titanium Bucket



**Quartz Bucket** 





# HUMBOLDT VAPE TECH

Hyperion

Instruction Manual

# Thank you for choosing the Hyperion from Humboldt Vape Tech! Here are some tips to get you started:

### ON/OFF:

Click the power button five times to turn the device on and off. When the unit is powered on the light will show your battery level: Full—Green, Half—White, Low—Blue, Very Low—Red.

# **Changing Heat Settings:**

Click the power button three times to shuffle through the heat settings. Low—Red, Medium—Blue, Medium/High—White, High—Green.

#### How to use:

AVS HexCore: Click the power button two times to engage preheat. The device will vibrate when ready for use. After 60 seconds the device heating cycle will time out. For a short session pulse the button eight to ten seconds for several cycles. The device has a 15 second time out warning when you hold the power button down.

Titanium & Quartz Buckets: Click the power button two times to engage preheat. The device will vibrate when ready for use. To extend heat sessions hold power button down for eight to ten seconds to heat the Hyperion for several cycles. The device has a 15 second time out warning when you hold the power button down.

#### To Clean:

Use cotton swabs to clean out the Titanium & Quartz Buckets between sessions. May soak all coils in >/= 90% ISO. Let air dry for at least 24 hours before use.

# Charging:

Plug the USB-C cable into the charging port and connect to the providing charging brick for the fastest charge. Unit requires approximately 1 hour and 45 minutes for a full charge.

Light will flash red while charging and will turn to green when it is fully charged.

All Sequoia Atomizer coils are compatible with the Hyperion.

# Package Contents:

- One (1) Hyperion Power Base
- One (1) Glass Top Bubbler
- One (1) Glass Carb Cap
- One (1) Silicone Cap Lanyard
- One (1) Silicone Power Base Cover
- One (1) Cap Base
- One (1) AVS Hexcore Coil
- One (1) Quartz Bucket
- One (1) Titanium Bucket
- One (1) Silicone Container
- One (1) USB-C Cable and Charging Block
- One (1) Dab Tool
- Two (2) Replacement 0-rings for Cape Base
- Five (5) Cotton Swabs
- Two (2) Alcohol Wipes
- One (1) Carrying Case

ONE YEAR MANUFACTURER WARRANTY.